

<b>No of measuring point</b>	<b>x [mm]</b>	<b>y [mm]</b>	<b>z [mV] background</b>	<b>z [mV] measurement</b>
<b>1</b>	33	61	0.98099	1.0279
<b>2</b>	43	58	1.0593	1.0759
<b>3</b>	23	52	1.0155	1.0615
<b>4</b>	12	43	0.96372	1.0024
<b>5</b>	23	41	1.0234	1.0303
<b>6</b>	30	46	0.945	1.0102
<b>7</b>	36	46	0.99474	1.0425
<b>8</b>	43	46	1.0238	1.0308
<b>9</b>	49	46	1.0273	1.0671
<b>10</b>	60	50	1.0643	1.0835
<b>11</b>	56	42	0.96283	1.0112
<b>12</b>	61	42	1.0487	1.0754
<b>13</b>	4	32	0.93159	0.94706
<b>14</b>	13	29	0.92117	0.9217
<b>15</b>	19	29	0.9529	0.95545
<b>16</b>	25	29	0.95313	0.95388
<b>17</b>	37	23	0.93909	0.96832
<b>18</b>	47	34	0.93558	0.98647
<b>19</b>	51	24	0.94699	0.99954
<b>20</b>	62	32	0.95425	1.0498
<b>21</b>	19	18	0.95858	0.98644
<b>22</b>	29	18	0.98481	1.0167
<b>23</b>	47	16	1.0144	1.0578
<b>24</b>	40	10	0.97427	1.0002
<b>25</b>	32	4	0.97918	0.98618